CHELLANAM GROYNES—PRESENT CONDITION OF

200. Mr. A. B. Salem *(Mattancheri):* Will the Government be pleased to state the condition of the two granite groynes put in Chellanam Village for preventing erosion of the Sea?

Mr. V. K. Aravindaksha Menon *(Chief Engineer):*

The groynes require certain repairs. These will be attended to next year if it is not possible to do so this year.

Mr. A. B. Salem *(Mattancheri):* Has anything been done?

Mr. V. K. Aravindaksha Menon *(Chief Engineer):* It is only yesterday that I have asked them to repair the groyne even this year itself.

LIBRARY ARCHIVES Kerala Legislative Assembly